

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
10/743,458	12/23/2003	Tsuyoshi Kubota	90606.2/wa	8146
54071 YAMAHA HA	7590 01/11/2008 TSUDOKI KABUSHIK	EXAMINER		
C/O KEATING & BENNETT, LLP			KIM, CHONG HWA	
8180 GREENS SUITE 850	8180 GREENSBORO DRIVE SUITE 850		ART UNIT	PAPER NUMBER
MCLEAN, VA	. 22102		3682	
			NOTIFICATION DATE	DELIVERY MODE
			01/11/2008	ELECTRONIC

# Please find below and/or attached an Office communication concerning this application or proceeding.

The time period for reply, if any, is set in the attached communication.

Notice of the Office communication was sent electronically on above-indicated "Notification Date" to the following e-mail address(es):

JKEATING@KBIPLAW.COM uspto@kbiplaw.com

•						
	Application No.	Applicant(s)				
	10/743,458	KUBOTA ET AL.				
Office Action Summary	Examiner	Art Unit				
	Chong H. Kim	3682				
The MAILING DATE of this communication app Period for Reply	ears on the cover sheet with the c	orrespondence address				
A SHORTENED STATUTORY PERIOD FOR REPLY WHICHEVER IS LONGER, FROM THE MAILING DA - Extensions of time may be available under the provisions of 37 CFR 1.13 after SIX (6) MONTHS from the mailing date of this communication If NO period for reply is specified above, the maximum statutory period w - Failure to reply within the set or extended period for reply will, by statute, Any reply received by the Office later than three months after the mailing earned patent term adjustment. See 37 CFR 1.704(b).	ATE OF THIS COMMUNICATION 36(a). In no event, however, may a reply be tin will apply and will expire SIX (6) MONTHS from a cause the application to become ABANDONE	N. nety filed the mailing date of this communication. D (35 U.S.C. § 133).				
Status						
1)⊠ Responsive to communication(s) filed on 27 De	ecember 2007.					
2a) ☐ This action is <b>FINAL</b> . 2b) ☒ This						
3) Since this application is in condition for allowar	3) Since this application is in condition for allowance except for formal matters, prosecution as to the merits is					
closed in accordance with the practice under Ex parte Quayle, 1935 C.D. 11, 453 O.G. 213.						
Disposition of Claims						
4) ☐ Claim(s) 1-12,14-20 and 22-24 is/are pending if 4a) Of the above claim(s) is/are withdraw 5) ☐ Claim(s) is/are allowed.  6) ☐ Claim(s) 1-12,14-20 and 22-24 is/are rejected.  7) ☐ Claim(s) is/are objected to.  8) ☐ Claim(s) are subject to restriction and/or	vn from consideration.					
Application Papers						
9) The specification is objected to by the Examine 10) The drawing(s) filed on 23 December 2003 is/al Applicant may not request that any objection to the Replacement drawing sheet(s) including the correct 11) The oath or declaration is objected to by the Ex	re: a) $\square$ accepted or b) $\boxtimes$ object drawing(s) be held in abeyance. See ion is required if the drawing(s) is obj	e 37 CFR 1.85(a). lected to. See 37 CFR 1.121(d).				
Priority under 35 U.S.C. § 119						
<ul> <li>12) Acknowledgment is made of a claim for foreign priority under 35 U.S.C. § 119(a)-(d) or (f).</li> <li>a) All b) Some * c) None of:</li> <li>1. Certified copies of the priority documents have been received.</li> <li>2. Certified copies of the priority documents have been received in Application No.</li> <li>3. Copies of the certified copies of the priority documents have been received in this National Stage application from the International Bureau (PCT Rule 17.2(a)).</li> <li>* See the attached detailed Office action for a list of the certified copies not received.</li> </ul>						
Attachment(s)  1) Notice of References Cited (PTO-892)  2) Notice of Draftsperson's Patent Drawing Review (PTO-948)  3) Information Disclosure Statement(s) (PTO/SB/08)  Paper No(s)/Mail Date	4) Interview Summary Paper No(s)/Mail Da 5) Notice of Informal P 6) Other:	ate				

Art Unit: 3682

#### **DETAILED ACTION**

#### Continued Examination Under 37 CFR 1.114

1. A request for continued examination under 37 CFR 1.114, including the fee set forth in 37 CFR 1.17(e), was filed in this application after final rejection. Since this application is eligible for continued examination under 37 CFR 1.114, and the fee set forth in 37 CFR 1.17(e) has been timely paid, the finality of the previous Office action has been withdrawn pursuant to 37 CFR 1.114. Applicant's submission filed on 12/27/07 has been entered.

## **Drawings**

2. The drawings are objected to under 37 CFR 1.83(a). The drawings must show every feature of the invention specified in the claims. Therefore, the different shapes of valley as recited in claims 16-20 must be shown or the feature(s) canceled from the claim(s). No new matter should be entered. (Note: the drawings are objected because the independent claim recites that the groove has a pair of parallel walls with an arc which reads on Figs. 6A and 6B. Claims 16-20 read on Figs. 9-13. However, Figs. 9-13 do not show parallel walls.)

Corrected drawing sheets in compliance with 37 CFR 1.121(d) are required in reply to the Office action to avoid abandonment of the application. Any amended replacement drawing sheet should include all of the figures appearing on the immediate prior version of the sheet, even if only one figure is being amended. The figure or figure number of an amended drawing should not be labeled as "amended." If a drawing figure is to be canceled, the appropriate figure must be removed from the replacement sheet, and where necessary, the remaining figures must

Art Unit: 3682

be renumbered and appropriate changes made to the brief description of the several views of the drawings for consistency. Additional replacement sheets may be necessary to show the renumbering of the remaining figures. Each drawing sheet submitted after the filing date of an application must be labeled in the top margin as either "Replacement Sheet" or "New Sheet" pursuant to 37 CFR 1.121(d). If the changes are not accepted by the examiner, the applicant will be notified and informed of any required corrective action in the next Office action. The objection to the drawings will not be held in abeyance.

### Claim Rejections - 35 USC § 103

- 3. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
  - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 4. Claims 1, 2, 7-12, 14, 15-20, and 22-24 are rejected under 35 U.S.C. 103(a) as being unpatentable over Mukai et al., U.S. Patent 4,693,139.

Mukai et al. shows, in Figs. 1-6, an engine having a split type connecting rod, the connecting rod comprising: a crank-pin hole (see Fig. 1); a valley 112, 122 formed on an inner circumferential surface 7 of the crank-pin hole; a fracture starting point groove 111, 121 formed at the base portion of the valley; wherein a width of the fracture starting point groove is less than a width of the valley (see Fig. 6); wherein the split type connecting rod is a nut-less type of connecting rod that is made of a forged material (col. 3, line 8); further comprising a small end portion 1 and a large end portion 2, wherein the large end portion includes the valley and the

Application/Control Number:

10/743,458

Art Unit: 3682

fracture starting point groove is formed in the large end portion; further comprising a rod portion 3 and a cap portion 2 sub 2; wherein a pair of the fracture starting point grooves are formed on the inner circumferential surface of the crank-pin hole; wherein an angle relative to a predetermined fracture plane passing from a shaft center of the crank-pin hole through a bottom portion in a bottom surface of the pair of fracture starting point groove and the valley is approximately 45 degrees (see Fig. 6 and col. 3, lines 36-47); wherein an interior angle of the valley is approximately 90 degrees (see Fig. 6 and col. 3, lines 36-47); wherein a cross section of the valley is larger than a cross section of the fracture starting point groove (see Fig. 6); wherein the bottom surface of the groove includes a bottom surface forms an arc with a radius (Fig. 6); and wherein the valley includes a pair of sloped portions 112, 122; but fails to show the surfaces of the groove being parallel to the fracture plane, different shapes of the valley surface as recited in claims 16-20, the ratio H/R, and a vehicle.

It would have been an obvious matter of design choice to make the surfaces of the fracture starting point groove of Mukai et al. parallel to the fracture plane, since such a modification would have involved a mere change in the shape of the groove. A change in size or shape is generally recognized as being within the level of ordinary skill in the art. In re Rose, 105 USPO 237 (CCPA 1955). Furthermore, a discovery of optimum range within prior art general conditions is also generally recognized as being within the level of ordinary skill in the art. In re Aller et al., 105 USPO 233.

As to the matter of the shapes of the sloped portions of the valley, it would have been an obvious matter of design choice to make the shape of the sloped portions of the valley of Mukai et al. with either curved, swelled and rounded, concaved, or rectilinear shape, since such a

modification would have involved a mere change in the shape of the valley. A change in size or shape is generally recognized as being within the level of ordinary skill in the art. *In re Rose*, 105 USPQ 237 (CCPA 1955).

As to the matter of the ratio H/R being between 1 to 10, it would have been obvious matter of design choice to provide such range in Mukai et al. A discovery of optimum range within prior art general conditions is generally recognized as being within the level of ordinary skill in the art. *In re Aller et al.*, 105 USPQ 233

As to the matter of the connecting rod being used in a vehicle, it would have been obvious to a person of ordinary skill in the art to apply the connecting rod as disclosed by Mukai et al. in a vehicle since it is well known in the art of engine that the connecting rod of Mukai et al. is made for engine and usually the engine is used in vehicles.

5. Claims 1-3, 7-12, 14, 15-20, and 22-24 are rejected under 35 U.S.C. 103(a) as being unpatentable over Spurny, U.S. Patent 6,125,536.

Spurny shows, in Figs. 1-5, a split type connecting rod comprising: a crank-pin hole 9; a valley D formed on an inner circumferential surface of the crank-pin hole; a fracture starting point groove 13 formed at the base portion of the valley and includes a bottom surface forms an arc with a radius (Fig. 3); wherein a width of the fracture starting point groove is less than a width of the valley; wherein the valley is formed such that the base portion is located at a position where a ratio of a depth of the fracture starting point groove to a shortest distance from an opening of the fracture starting point groove to a bolt hole 11 (as measured at the mid-portion of the valley D in Fig. 2) is about 70% or more; wherein the split type connecting rod is a nutless type of connecting rod that is made of a case material (see Abstract); further comprising a

Art Unit: 3682

small end portion 1 and a large end portion 5, wherein the large end portion includes the valley and the fracture starting point groove is formed in the large end portion; further comprising a rod portion 3 and a cap portion; wherein a pair of the fracture starting point grooves are formed on the inner circumferential surface of the crank-pin hole; wherein a cross section of the valley is larger than a cross section of the fracture starting point groove; and wherein the valley includes a pair of sloped portions; but fails to show the surfaces of the groove being parallel to the fracture plane, the surface of the valley being about 45 degrees measured from the fracture plane, different shapes of the valley surface as recited in claims 16-20, and the ratio H/R, and a vehicle.

It would have been an obvious matter of design choice to make the surfaces of the fracture starting point groove of Spurny parallel to the fracture plane and the interior angle of the valley having 90 degrees, since such a modification would have involved a mere change in the shape of the groove or the valley. A change in size or shape is generally recognized as being within the level of ordinary skill in the art. In re Rose, 105 USPQ 237 (CCPA 1955). Furthermore, a discovery of optimum range within prior art general conditions is also generally recognized as being within the level of ordinary skill in the art. In re Aller et al., 105 USPQ 233.

As to the matter of the shapes of the sloped portions of the valley, it would have been an obvious matter of design choice to make the shape of the sloped portions of the valley of Spurny with either curved, swelled and rounded, concaved, or rectilinear shape, since such a modification would have involved a mere change in the shape of the valley. A change in size or shape is generally recognized as being within the level of ordinary skill in the art. In re Rose, 105 USPQ 237 (CCPA 1955).

Application/Control Number:

10/743,458 Art Unit: 3682

As to the matter of the ratio H/R being between 1 to 10, it would have been obvious matter of design choice to provide such range in Spurny. A discovery of optimum range within prior art general conditions is generally recognized as being within the level of ordinary skill in the art. *In re Aller et al.*, 105 USPQ 233

As to the matter of the connecting rod being used in a vehicle, it would have been obvious to a person of ordinary skill in the art to apply the connecting rod as disclosed by Spurny in a vehicle since it is well known in the art of engine that the connecting rod of Spurny is made for engine and usually the engine is used in vehicles.

6. Claims 1, 2, 4-12, 14-20, and 22-24 are rejected under 35 U.S.C. 103(a) as being unpatentable over Ishida et al., U.S. Patent 6,312,159 B1 in view of Mukai et al.

Ishida et al. shows, in Figs. 1, 2, and 7, an engine (col. 1, line 17) having a split type connecting rod, the connecting rod comprising: a crank-pin hole 1d; a fracture starting point groove 21; further comprising a bearing locking groove 5a, 5b, 6a, 6b provided on the inner circumferential surface of the crank-pin hole, wherein the valley is formed at a position opposite to the bearing locking groove provided on the inner circumferential surface of the crank-pin hole; wherein the bearing locking groove includes a pair of concave portions located at positions that are deviated in the circumferential direction of the inner circumferential surface of the crank-pin hole; wherein the split type connecting rod is a nut-less type of connecting rod that is made of a cast material (die-formed); further comprising a small end portion 1b and a large end portion 1a, wherein the large end portion includes the fracture starting point groove is formed in the large end portion; further comprising a rod portion 1c and a cap portion 3; and wherein a pair of the

Application/Control Number:

10/743,458 Art Unit: 3682

fracture starting point grooves are formed on the inner circumferential surface of the crank-pin hole; but fails to show the surfaces of the groove being parallel to the fracture plane, a valley having surfaces positioned about 45 degrees measured from the fracture plane, different shapes of the valley surface as recited in claims 16-20, and the ratio H/R, and a vehicle.

Mukai et al. shows, in Fig. 6, a split type connecting rod comprising a valley 112, 122 formed on an inner circumferential surface 7 of the crank-pin hole; a fracture starting point groove 111, 121 formed at the base portion of the valley; wherein a width of the fracture starting point groove is less than a width of the valley (see Fig. 6); wherein an angle relative to a predetermined fracture plane passing from a shaft center of the crank-pin hole through a bottom portion in a bottom surface of the pair of fracture starting point groove and the valley is approximately 45 degrees (see Fig. 6 and col. 3, lines 36-47); wherein an interior angle of the valley is approximately 90 degrees (see Fig. 6 and col. 3, lines 36-47); wherein a cross section of the valley is larger than a cross section of the fracture starting point groove (see Fig. 6); and wherein the valley includes a pair of sloped portions 112, 122.

It would have been obvious to a person of ordinary skill in the art at the time the invention was made to modify the shape of the fracture starting configuration of Ishida et al. by providing the valley as taught by Mukai et al. in order to effectively prevent the damages or generating cut power on the reverses of the split metals, as described from col. 3, line 48 to col. 4, line 3 by Mukai et al.

As to the matter of the shapes of the sloped portions of the valley, it would have been an obvious matter of design choice to make the shape of the sloped portions of the valley of Mukai e tal. with either curved, swelled and rounded, concaved, or rectilinear shape, since such a

Art Unit: 3682

modification would have involved a mere change in the shape of the valley. A change in size or shape is generally recognized as being within the level of ordinary skill in the art. *In re Rose*, 105 USPQ 237 (CCPA 1955).

As to the matter of the surfaces of the groove having a surface that is parallel to the fracture plane, it would have been an obvious matter of design choice to make the angle of fracture starting point groove of Ishida et al. parallel to the fracture plane, since such a modification would have involved a mere change in the shape of the groove. A change in size or shape is generally recognized as being within the level of ordinary skill in the art. *In re Rose*, 105 USPQ 237 (CCPA 1955). Furthermore, a discovery of optimum range within prior art general conditions is also generally recognized as being within the level of ordinary skill in the art. *In re Aller et al.*, 105 USPQ 233.

As to the matter of the bottom surface of the groove having an arc shape, it would have been obvious to make the sharp bottom groove with a rounded surface since it is a common knowledge that a fracture starting point can be easily made from either rounded surface or sharp indented surface and such method would be within the level of ordinary skill in the art.

As to the matter of the ratio H/R being between 1 to 10, it would have been obvious matter of design choice to provide such range in Mukai et al. A discovery of optimum range within prior art general conditions is generally recognized as being within the level of ordinary skill in the art. *In re Aller et al.*, 105 USPQ 233

As to the matter of the connecting rod being used in a vehicle, it would have been obvious to a person of ordinary skill in the art to apply the connecting rod as disclosed by Ishida

Art Unit: 3682

et al. in a vehicle since it is well known in the art of engine that the connecting rod of Ishida et al. is made for engine and usually the engine is used in vehicles.

### Response to Arguments

7. Applicant's arguments with respect to claims 1-12, 14-20, and 22-24 have been considered but are most in view of the new ground(s) of rejection.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Chong H. Kim whose telephone number is (571) 272-7108. The examiner can normally be reached on Monday - Friday; 9:00 - 5:00.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Richard Ridley can be reached on (571) 272-6917. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

chk

January 7, 2008


CHONG H. KIM

Application No. 10/743,458
July 13, 2007
Reply to the Office Action dated April 11, 2007
Page 15 of 15

## **New Sheet**

# Figure 19

500



OK to enter, ch